





MDP Sec #1




Identification



Location	Main electrical
Equipment	MDP Sec #1
Additional information	Feeds Panel 'C'
Date	2/25/2009
Time	9:30:33 AM

Fault description



Fault	Heat
Fault Temperature	123.0°F
Reference Temp	79.5°F
Difference	43.5°F

Recommendation

Repair

Bus connection is loose. Requires outage to repair.

